V-1230
Permanent Instructions

OVVO

1. Milling

(i) Plunge
(ii) Travel
(iii) Out

Depth

Travel

30

9.4

Recommended Spacing
(a): 35mm to 80mm
(b): 150mm to 350mm

(b)

(b)

(a)

Recommended Settings
Depth: 12.5mm, +/- 0.5mm
Travel Centre to Centre: 20.5mm (min) - 20.7mm
Rotation Speed: CNC speeds vary with different
materials. Maximum cutter rotation: 18,000

2. Housing

Push into place

V-1230PH

V-1230PC

V-1230PH

V-1230PH

V-1230PH

V-1230PH

V-1230PH

Scan for

animation

3. Assembly - Simply push into place to connect

V-1230PH

V-1230PC

V-1230PH

V-1230PH

How it works