


## ASSEMBLY SOLUTIONS



The door height to be decreased by 25mm  
The upper panel depth to be decreased by 27mm