


ART. 852HB119

AP1003

C · 2 x 	Y · 2 x 	L · 2 x  6x16 plastic	M · 4 x  6x18 metal
N · 4 x  TB 6x12	X · 2 x  TB 6x16	P · 2 x  TPS 6x15	Q · 6 x  4x20
G · 2 x  Ø16x20	U · 2 x  Ø16x6		

AP1004

O · 24 x  TP 6x50	P · 18 x  TPS 6x15
---	--

AP1021

AA · 4 x 	BB · 4 x 	CC · 4 x  rubber pad
--	--	--

AP1020


EE · 4 x  TPS 6x20	FF · 2 x  TPS 4x15
---	--

AP1000

S · 2 x  magnet	V · 2 x  TS 3.5x16	T1 · 3 x  TS 4x35
---	--	---

ART. 852HB119

AP1012

MM · 4x  TP 6x20	SS · 12 x  TS 2,5x18	I · 1 x 	HH · 5 x 
GG · 2 x 			

AP1013

II · 2 x  24x10 plastic	L · 4 x  16x6 plastic	NN · 4 x  TP 6x15	N · 2 x  TB 6x12
P · 4 x  TPS 6x10	QQ · 10 x  TP 6x30	LL · 2 x  Ø10x6	

n.5 AP1009

R · 4 x  6MA
--

AP1014

R · 10 x  6MA

AP1016

R · 12 x  6MA	R1 · 18 x  6MA
--	--