





Installation Guide 90D 98 - Metric







Mark center line on both substrates. The 90D 98 works on box joints (shown), t-section and mitered joints. Mark mounting screw centre points by measuring or with the aid of the Mark-Out Template.







An alternative to marking screw locations is to apply glue to the mounting faces of the Hooks to aid with placement. Line up notches in the Hooks with the marked lines them press and hold the assembled 90D in place. Allow time for glue to dry.









Install the Key remembering it only needs to travel 1 pitch for full engagement. Use the padlock symbol as a guide. The Key is also bidirectional and can be installed either end, see step 6b.




Installation Aids





Visit joinlox.com/striplox or call 1800 JOINLOX to find out more about these installation aids.

Load Capacity





Direction	Indic. Load Capacity
А	200 kg
В	66 kg
С	200 kg
С	200 kg

- Tested using particle board and fixed with screws.
- Ensure sufficient screw embedment in substrate.




Installation Guide 90D 98 - US







Mark center line on both substrates. The 90D 98 works on box joints (shown), t-section and mitered joints. Mark mounting screw centre points by measuring or with the aid of the **Mark-Out Template**.





Fasten each Hook with 3 x 8G screws. Ensure sufficient screw embedment in substrate.




An alternative to marking screw locations is to apply glue to the mounting faces of the Hooks to aid with placement. Line up notches in the Hooks with the marked lines them press and hold the assembled 90D in place. Allow time for glue to dry.








Install the Key remembering it only needs to travel 1 pitch for full engagement. Use the padlock symbol as a guide. The Key is also bidirectional and can be installed either end, see step 6b.



Installation Aids






delivers a strong and reliable connection between Striplox

products and most substrates.

Visit joinlox.com/striplox or call 1800 JOINLOX to find out more about these installation aids.

Load Capacity



Direction	Indic. Load Capacity
А	440 lb
В	145 lb
С	440 lb

- Tested using particle board and fixed with screws.
- Ensure sufficient screw embedment in substrate.