




Workbench Caster Kit Mounting Instruction

Loading capacity: 65 kg per caster



Installation

1. Mark and drill pilot holes for mounting brackets.
2. Fix mounting brackets to workbench legs with provided screws.
3. Install casters to mounting brackets with provided nuts.

Use

1. Press down each caster lift with foot until it fully seizes the mechanism and raises the workbench.
2. Put the workbench in position and lift up each caster lift with foot to release the mechanism and lower the workbench.