













ART. 8410012


AP1003

C	· 2 x	Y	· 2 x	L	· 2 x	M	· 4 x
					6x16 plastic		6x18 metal
N	· 4 x	X	· 2 x	P	· 2 x	Q	· 6 x
	TB 6x12		TB 6x16		TPS 6x15		4x20
G	· 2 x	U	· 2 x				
	Ø16x20		Ø16x6				




AP1005

O	· 12 x	P	· 18 x
	TP 6x50		TPS 6x15




AP1011

R	· 30 x
	compass 6 MA

AP1021

AA	· 4 x	BB	· 4 x	CC	· 4 x
					rubber pad

AP1000

S	· 2 x	V	· 2 x	T1	· 3 x
	magnet		TS 3.5x16		TS 4x35